HAER NY, 16-TAHA,

HISTORIC AMERICAN ENGINEERING RECORD

MASTER PROJECT RECORD

HAER NY-123

Adirondack Iron and Steel Company: "New Furnace," 1849-1854.
Tahawus
Essex County
New York

- NY-123-1 Photocopied June 1978.

 SAWMILL AT UPPER WORKS, WITH BREAST WHEEL. PERHAPS DATES TO 1830'S. VIEW TAKEN CA. 1890'S. SOURCE: MCINTYRE DEVELOPMENT, NL INDUSTRIES, TAHAWUS, N.Y.
- NY-123-2 Photocopied June 1978
 "THE IRON DAM." VIEW OF THE IRON DAM, THE OUTCROPPING OF THE ORE FOUND IN 1826 BY HENDERSON. FURNISHED WATER TO SAWMILL. SOURCE:
 BENSON LOSSING, THE HUDSON, FROM THE WILDERNESS TO THE SEA, TROY,
 NEW YORK, 1866, p. 25
- NY-123-3 Photocopied June 1978
 "ADIRONDACK VILLAGE." ENCRAVING MADE IN 1859, LOOKING DOWN MAIN
 STREET. SOURCE: BENSON LOSSING, THE HUDSON, FROM THE WILDERNESS
 TO THE SEA, TROY, NEW YORK, 1866, p. 27.
- NY-123-4 Photocopied June 1978
 R.H. ROBERTSON, PENCIL AND CHARCOAL SKETCH, LAKE HENDERSON, FROM TAHAWUS CLUB BOAT DOCK. CA. 1914. SOURCE: ARTHUR CROCKER, PRESIDENT OF THE TAHAWUS CLUB.
- NY-123-5 Photocopied June 1978
 R.H. ROBERTSON WATER COLOR, CA. 1915. MACNAUGHTON COTTAGE OF UPPER WORKS. SOURCE: ARTHUR CROCKER, TAHAWUS CLUB.
- NY-123-6 Jet Lowe, Photographer, June 1978.

 MACNAUGHTON COTTAGE. BANK WAS IN THE RIGHT WING OF THE BUILDING.

 THIS IS THE ONLY 1840'S BUILDING STILL STANDING IN THE VILLAGE.
- NY-123-7 Photocopied June 1978
 R.H. ROBERTSON, WATER COLOR, CA. 1915. CAMP AT TAHAWUS CLUB.
 SOURCE: ARTHUR CROCKER, TAHAWUS CLUB.
- NY-123-8 Photocopied June 1978
 R.H. ROBERTSON, WATER COLOR, CA. 1915. TIMBER CRIB BRIDGE ACROSS
 HUDSON RIVER AT LOWER WORKS. SOURCE: ARTHUR CROCKER, TAHAWUS
 CLUB.
- NY-123-9 Photocopied June 1978
 R.H. ROBERTSON, WATER COLOR, CA. 1915. LAKE SANFORD WINTER.
 SOURCE: ARTHUR CROCKER, TAHAWUS CLUB.

Adirondack Iron and Steel Co. HAER No. NY-123 Index to photographs Page 2

- NY-123-10 Photocopied June 1978.
 STACK AT THE "NEW"FURNACE, CA. 1900. SOURCE UNKNOWN.
 OBTAINED FROM TAHAWUS CLUB.
- NY-123-11 Photocopied June 1978.

 HOT BLAST STOVE ON "NEW" FURNACE. NOTE DOWNCOMER ON
 LEFT AND DAMPERS ON CHIMNEYS. CA. 1906.

 SOURCE: MACINTYRE DEVELOPMENT, NL INDUSTRIES, TAHAWUS, N.Y.
- NY-123-12 Photocopied June 1978.

 R.H. ROBERTSON WATER COLOR PAINTING, CA. 1918. VIEW OF THE "NEW" FURNACE FROM SOUTH.

 SOURCE: ARTHUR CROCKER, TAHAWUS CLUB.
- NY-123-13 Photocopied June 1978.

 R.H. ROBERTSON WATER COLOR, LAKE HARKNESS, CA. 1915.

 SOURCE: ARTHUR CROCKER, TAHAWUS CLUB.
- NY-123-14 Jet Lowe, Photographer, June 1978.

 MCINTYRE IRON WORKS. VIEW SOUTHEAST OF TOWER.
- NY-123-15 Photocopied June 1978.

 WHEEL HOUSE RUINS OF "NEW" FURNACE. SEGMENT GEAR
 REMNANTS VISIBLE STANDING IN WHEEL PIT IN FOREGROUND.

 SOURCE: MCINTYRE DEVELOPMENT, NL INDUSTRIES, TAHAWUS, N.Y.
- NY-123-16 Jet Lowe, Photographer, June 1978.
 MCINTYRE IRON WORKS. VIEW NORTH TOWARDS WHEEL PIT,
 CRANKSHAFTS IN THE FOREGROUND.
- NY-123-17 Jet Lowe, Photographer, June 1978.
 MCINTYRE IRON WORKS.WHEELHOUSE, FOREBAY, SOUTH VIEW
 OF BLOWING ENGINES.
- NY-123-18 Jet Lowe, Photographer, June 1978.
 MCINTYRE IRON WORKS. WHEELHOUSE, NORTH VIEW, BLOWERS
 FROM THE TAILRACE.
- NY-123-19 Jet Lowe, Photographer, June, 1978.
 MCINTYRE IRON WORKS, DETAIL BLOWING ENGINE, FROM
 THE TAILRACE.
- NY-123-20 Jet Lowe, Photographer, June, 1978.
 MCINTYRE IRON WORKS. BACK SIDE OF BLOWING ENGINES,
 FROM TAILRACE.
- NY-123-21 Jet Lowe, Photographer, June 1978.
 MCINTYRE IRON WORKS. WHEELHOUSE, BLOWERS WITH PISTON
 AND CONNECTING ROD.

Adirondack Iron and Steel Co. HAER No. NY-123
Index to Photographs Page 3

- NY-123-22 Jet Lowe, Photographer, June, 1978.
 WHEELHOUSE, MCINTYRE IRON WORKS, TAILRACE, SOUTHEAST VIEW, RIVERSIDE WALL.
- NY-123-23 Jet Lowe, Photographer, June, 1978.
 WHEELHOUSE, MCINTYRE IRON WORKS, GENERAL VIEW, SOUTH.
- NY-123-24 Jet Lowe, Photographer, June, 1978.
 FRONT ELEVATION OF THE STACK, WITH HOT BLAST STOVE IN VIEW.
- NY-123-25 Jet Lowe, Photographer, June, 1978.
 BINDERS ON THE STACK, TIEBARS AND ANCHORS.
- NY-123-26 Jet Lowe, Photographer, June, 1978.
 MCINTYRE IRON WORKS, DETAIL BRICKWORK OF ARCH.
- NY-123-27 Jet Lowe, Photographer, June, 1978.
 MCINTYRE IRON WORKS. EAST PORTAL FURNACE.
- NY-123-28 Jet Lowe, Photographer, June, 1978.
 MCINTYRE IRON WORKS. EAST PORTAL FURNACE.
- NY-123-29 Jet Lowe, Photographer, June, 1978. MCINTYRE IRON WORKS. SOUTH PORTAL.
- NY-123-30 Jet Lowe, Photographer, June, 1978. TUYERE ENTRY INTO THE FURNACE.
- NY-123-31 Jet Lowe, Photographer, June, 1978. ELEVATION OF HEARTH SIDE OF STOCK.
- NY-123-32 Jet Lowe, Photographer, June, 1978.
 RUINS OF WATERWHEELS AND CRANK-END VIEW OF BLOWERS.